SAILING DIRECTIONS CORRECTIONS

PUB 172 9 Ed 2001 LAST NM 29/03

Page 210—Lines 50 to 53/L; read:

inside the harbor entrance; caution is necessary as depths of as little as 13.3m lie inside the edges of the dredged channel.

Dredging is underway (2003) in the access channel. The channel is being deepened to 17m and widened to 325m. This will allow for two-way traffic in the channel.

The harbor is divided into two basins. The outer basin,

(BA NM 26/03, Section IV) 31/03