SAILING DIRECTIONS CORRECTIONS

PUB 172 9 Ed 2001 LAST NM 22/02

Page 176—Line 19/L; insert after:

Nancowry Shoal, with a least depth of 10m, lies 2 miles SW of Ras Muari.

(BA NP 38) 24/02

Page 177—Line 42/L; insert after:

It has been reported (2002) that a Pakistani naval base is being developed in the East Bay.

(BA NP 38) 24/02

Page 178—Line 18/R; read:

Katagar is very uneven in depths of less than 20m. An aero light, with a radiobeacon, is shown 5 miles NE of Ras Jiwani.

(BA NP 38) 24/02